Date:	2/17/2016				
take no respo	ensibility for problems discovered	after the insp	ection dat	. The City of Milwaukee, the Redevelopment Authore, or for omissions through error or oversight. The I eral Block Grant or HOME programs.	
Exterior (Condition Report				
Location Site	Required Work Landscaping	n/a_ ☑	Yes □	Note/Comments Self Help	\$ Cost
	Steps/Handrails	n/a ☑	Yes □		\$
	Service walks	n/a □	Yes ☑	assumed - snow covered	\$ 900.00
	Fencing	n/a ☑	Yes □		\$
	Parking	n/a □	Yes ☑	assumed - snow covered	\$ 3,500.00
	Retaining walls	n/a □	Yes 🗸	front elevation (includes fencing)	\$ 2,400.00
	Other	n/a □	Yes □		\$
_	Other	n/a □	Yes □		\$
Garage	Singles: repair	n/a □	Yes □		\$
	Shingles: Roof over existing	n/a 🗆	Yes □		\$
	Shingles:Tear off & re-roof	n/a □	Yes □		\$
	Gutters/downspouts	n/a □	Yes □		\$
	Flashing	n/a 🔲	Yes □		\$
	Eaves	n/a □	Yes □		\$
	Siding	n/a 🗆	Yes □		\$
	Doors	n/a □	Yes □		\$
	Windows	n/a 🗆	Yes □		\$
	Slab	n/a □	Yes □		\$
	Paint	n/a 🗆	Yes □		\$
	Electrical	n/a □	Yes □		\$
	Other	n/a 🗆	Yes □		\$
Porches	Roof	n/a ☑	Yes 🗆		\$
	Deck-upper	n/a ☑	Yes 🗆		\$
	Decklower	n/a □	Yes 🗹	front porch	\$ 2,880.00
	Steps/handrails	n/a ☑	Yes 🗆		\$
	Ceiling	n/a ☑	Yes □		\$
	Guardrails	n/a ☑	Yes 🗆		\$
	Structural	n/a ☑	Yes 🗆		\$
	Paint	n/a 🔲	Yes 🗹		\$ 500.00
	Other	n/a 🗆	Yes 🗆		\$

1981-83 South Muskego Avenue

Other □

Scope of Work for Property Located at:

Property is: Single Family ☑ Duplex □

House

Chimney	n/a ☑	Yes □	_	\$
Shingles: repair	n/a □	Yes ☑		\$ 450.00
Shingles: Roof over existing	n/a ☑	Yes □		\$
Shingles:Tear off & re-roof	n/a ☑	Yes □		\$
Gutters/downspouts	n/a □	Yes ☑		\$ 700.00
Flashing	n/a ☑	Yes □		\$
Eaves	n/a ☑	Yes □		\$
Siding	n/a _☑	Yes □	_	\$
Storm Doors	n/a ☑	Yes □		\$
Prime ("main") Doors	n/a □	Yes ☑		\$ 700.00
Storm Windows	n/a ☑	Yes □		\$
Prime ("main") Windows	n/a □	Yes ☑		\$ 620.00
Paint	n/a □	Yes ☑	previously painted surfaces	\$ 1,800.00
Foundation	n/a _☑	Yes □		\$
Electrical	n/a ☑	Yes □		\$
Other	n/a □	Yes □		\$
Other	n/a □	Yes □		\$
Other	n/a □	Yes 🗆	_	\$
Other	n/a 🗆	Yes 🗆		\$

Exterior: Estimated Cost:* \$
*average contracted cost. Actual costs may vary. Self help will reduce the amount.

14,450.00

Interior Co	ondition Report					
	Unit: Entire unit (single family) Upper unit of duplex	✓		Lower unit of duplex Other		
Mechanical Heating	Required Work					
aug	Repair/replace boiler	n/a ☑	Yes □		\$	
	Repair radiation	n/a ☑	Yes □		\$	
	Repair/replace furnace	n/a ☑	Yes □		\$	
	Repair ductwork	n/a ☑	Yes □		\$	
	Replace thermostat	n/a ☑	Yes □		\$	
	Repair/replace grilles	n/a ☑	Yes □		\$	
Flootwinel	Tune boiler/furn. insp ht exchange	€n/a □	Yes ☑	boiler	\$	600.00
Electrical	Repair/replace receptacles	n/a □	Yes ☑		\$	300.00
	Repair/replace switches	n/a □	Yes ☑		\$	300.00
	Repair/replace fixtures	n/a □	Yes ☑	<u> </u>	\$	300.00
	Install outlets and circuits	n/a ☑	Yes □		\$	
	Install outlets and circuits	n/a ☑	Yes □		\$	
	Install outlets and circuits	n/a ☑	Yes □		\$	
	Install outlets and circuits	n/a ☑	Yes □		\$	
	Upgrade service	n/a ☑	Yes □		\$	
	Other	n/a □	Yes □		\$	
.	Other	n/a □	Yes □		\$	
Plumbing	Repair/replace kitchen sink	n/a ☑	Yes □		\$	
	Repair/replace kitchen sink fauce	en/a ☑	Yes □		\$	
	Repair/replace tub	n/a ☑	Yes □		\$	
	Repair/replace tub faucet	n/a ☑	Yes □		\$	
	Repair/replace toilet	n/a ☑	Yes □		\$	
	Repair/replace lavatory	n/a ☑	Yes □		\$	
	Repair/replace lavatory faucet	n/a ☑	Yes □		\$	
	Repair/replace wash tub	n/a ☑	Yes □		\$	
	Repair/replace wash tub faucet	n/a ☑	Yes □		\$	
	Unclog piping:	n/a □	Yes ☑	building drain	\$	500.00
	Repair drain/waste/vent piping	n/a 🗆	Yes ☑		\$	1,600.00
	Repair water piping	n/a 🗹	Yes □		\$	
	Repair/replace water heater	n/a ☑	Yes □	<u> </u>	\$	
	Other	n/a □	Yes 🗆		\$	

\$

n/a 🗆 Yes 🗆

Other

Windows								
	Replace broken glass	n/a <u></u> ✓	Yes □		\$			
_	Repair or replace sash	n/a ☑	Yes □		\$			
Doors	Repair or replace doors	n/a □	Yes 🗸		\$	760.00		
W. II. (0. III.	Repair or repl. locks/latches	n/a □	Yes 🗹	Self Help	\$	220.00		
Walls/Ceiling	Repair or repl. @ defective	n/a □	Yes 🗸		\$	3,800.00		
Paint	Repair or repl. @ defective	n/a □	Yes ☑		\$	1,900.00		
Fire Safety								
	Install smoke/CO alarm:bsmt.	n/a □	Yes 🗹	Self Help	\$	55.00		
	Install smoke/CO alarm: 1st flr.	n/a □	Yes ☑	Self Help	\$	165.00		
	Install smoke/CO alarm: 2nd flr.	n/a □	Yes ☑	Self Help	\$	165.00		
Handrails	Repair/replace defective	n/a □	Yes ☑	Self Help	\$	500.00		
Stairs	Repair defective	n/a □	Yes ☑	_	\$	1,700.00		
Floors	Repair defective	n/a □	Yes ☑	including structural @ bathroom	\$	3,000.00		
Other		n/a □	Yes ☑	remove kitchen from basement area and	\$	2,500.00		
		n/a □	Yes □	cap supply & waste piping (permit required)	\$			
		n/a □	Yes □		\$			
		n/a □	Yes 🗆		\$			
				Interior: Estimated Cost:	\$	18,365.00		
				Total Exterior and Interior Cost:*	\$	32,815.00		
			*average contracted cost. Actual costs may year. Calf help will reduce the amount					

^{*}average contracted cost. Actual costs may vary. Self help will reduce the amount.

Inspected by: Tom Frank Date: 2/11/16

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located at 7630 W. Mill Road.